



690 Chesterfield Pkwy W • Chesterfield MO 63017-0760 Phone: 636-537-4000 • Fax 636-537-4798 • www.chesterfield.mo.us

### **Planning Commission Staff Report**

**Project Type:** Amended Site Development Plan

Meeting Date: December 10, 2018

From: Mike Knight, Planner

**Location:** A 2 acre tract of land located southwest of the intersection of Olive

Boulevard and Chesterfield Parkway.

**Description:** YaYa's Euro Bistro (ASDP) An Amended Site Development Plan, Landscape

Plan, Architectural Elevations and Architect's Statement of Design for a 2 acre tract of land located southwest of the intersection of Olive Blvd and

Chesterfield Pkwy.

#### PROPOSAL SUMMARY

YaYa's Euro Bistro is proposing a 1,209 square foot banquet addition at the north of the existing facility with a pathway from the new addition to the existing patio. The exterior materials and colors would match the existing earth-tones of the facility. Due to the size of the proposed addition, review by the Architectural Review Board (ARB) was required and the meeting was held on October 11, 2018. A minor amount of site work will also be accomplished in conjunction with this request.

#### **HISTORY OF SUBJECT SITE**

In November of 1996, the City of Chesterfield City Council approved Ordinance 1206 which amended City of Chesterfield Ordinance 175 and repealed City of Chesterfield Ordinance 259 and established a "C-8" Planned Commercial District for a 3 acre tract of land.

In September 1998, the Site Development Plan for YaYa's was approved.

In September of 2001, the City of Chesterfield City Council approved Ordinance 1788. This was a change in zoning from a "C-2" Shopping District and "C-8" Planned Commercial District to a new "PC" Planned Commercial District for a 3.9 acre tract of land. The 3.9 acres include the current Junior Chamber International building and the YaYa's Euro Bistro. The subject site remains today zoned "PC" Planned Commercial District under the terms and conditions of City of Chesterfield Ordinance 1788.



Figure 1: Aerial Photo

#### **SURROUNDING LOCATIONS**

The subject site is located southwest of the intersection of Olive Boulevard and Chesterfield Parkway. Although the majority of this request is the 1,209 square foot banquet room addition, there is a minor amount of site work in conjunction with this request.

The subject site and all adjacent parcels are located in what is known as the Urban Core Land Use Designation within the City of Chesterfield's Comprehensive Plan. The access point for YaYa's is off of Olive Boulevard which is classified as a Major Arterial. Olive Boulevard is owned and operated by the Missouri Department of Transportation. To the north is a 3 story, 262,000 square foot Pfizer research facility which is currently under construction. The banquet room addition would primarily be seen by travelers on Olive Boulevard and from the Pfizer research facility. The rear of the building

Direction	Development	Zoning
North	Pfizer	C8
South	Junior Chamber International	PC
East	Gas/Car wash/ Fast Food	C8
West	Woodland	C8

Table 1: Surrounding Sites and Zoning

is woodland, to the south is the non-profit Junior Chamber International, and across Olive Boulevard is retail consisting of a gas station, car wash, and fast food building. Table 1 to the left outlines the surrounding sites in relation to Figure 1 above.




Figure 2: Color Site Plan

Figure 2 above is the Color Site Plan for the proposed development. The building is surrounded by parking with the access point for pedestrians at the front of the building. This addition does not change the parking, pedestrian connectivity, or vehicular circulation of the site. Landscaping has been removed in some areas and added in others as outlined later in this report.

#### **Current Conditions**

The existing restaurant building is a single story restaurant with EIFS facades and a standing seam metal roof which screens the roof top units. There is a patio at the north of the site surrounded by a low site wall. The area of the building facing the patio features a flat roof projecting out under the mansard with EIFS banding and dark-bronze framed storefront windows. The storefront windows are set in slight recesses giving the vertical EIFS pilasters between them a thickened appearance. Figure 3 on the following page shows recent photos of the area where the addition is being proposed.

There are two existing trees that currently reside in the area that will be removed, due to the construction of the addition. The mechanical units currently exist on the building roof behind the metal mansard and are fully screened. Any new mechanical units would be located in the same location as existing. The trash area is currently screened and located to the rear of the building on the southern/opposite end of the proposed addition.





Figure 3: Current Conditions

#### **Proposed Changes**

The applicant's goal for the banquet room addition is to make it look as if it has always been part of the building. The design replicates the design features of the area of the building facing the patio. The dark bronze framed storefront windows and thickened pilasters between will match the existing conditions. Glazing will match the existing panels at the patio. EIFS will be the new material on the facades with thickened EIFS bands to align with the existing building. The parapet and mansard roof will be extended around to the front to provide a cohesive appearance.

A portion of the site wall surrounding the patio will be removed and the patio extended in the area southeast of the banquet room addition to integrate the patio into the addition. Materials for the patio and new site wall surrounding the patio will match the existing, including finishes and height. A portion of the existing sidewalk along the northeast of the site will be removed for the installation of the addition and new landscape bed.





Figure 4: Proposed Changes

#### **Landscaping and Screening**

Two trees are to be removed from the banquet room addition. The applicant has provided a new planting list and proposed a new planting schedule consisting of 6 Serviceberry, 3 Boxwood, 5 Dwarf Fothergilla, and 68 Liriope, 1 Black gum, 1 Arborvite, and 1 Littleleaf Linden. The trash area is not being affected by this addition, but the applicant did provide a fresh application of paint that matches the existing building color. Figure 5 and Figure 6 below identify the proposed landscaping and the existing trash screening with updated paint.






Figure 5: Proposed Landscaping

Figure 6: Existing Screening

No exterior building lighting (other than an emergency fixture at the egress door) will be on the addition. No site lighting will be altered within this project. No exterior signage will be placed on the addition or added to the site. All existing signage is to remain.

#### ARCHITECTURAL REVIEW BOARD

The project was reviewed by the Architectural Review Board on Thursday October 11<sup>th</sup>, 2018. At that time, the Board made a motion and seconded the motion to forward the project to the Planning Commission as presented, with the following conditions:

- The proposed addition should continue the darker EIFS color and banding around the base of the addition similar to the existing building.
- The proposed addition should incorporate elements of the mansard roof, pilasters, and brackets similar to the existing building.

The motion was then amended recommending that the applicant also supply material samples for Planning Commission review. The motion passed by a voice vote of 6-0. The applicant has since stated material samples will be presented at the Planning Commission meeting.

Both of the ARB conditions were fulfilled. Figure 7 depicts the front of the building with the incorporated elements of the mansard roof, pilasters, and brackets similar to the existing building along with the darker EIFS color banding continuing around the base of the building. Figure 8 is the rear.



Figure 7: Updated Font



Figure 8: Updated Rear


#### **MOTION**


The following options are provided to the Architectural Review Board for consideration relative to this application:

- 1) "I move to approve (or deny) the Amended Site Development Plan, Amended Landscape Plan, Amended Architectural Elevations, and Architect's Statement of Design for YaYa's Euro Bistro"
- 2) "I move to approve the Amended Site Development Plan, Amended Landscape Plan, Amended Architectural Elevations, and Architect's Statement of Design for YaYa's Euro Bistro with the following conditions... " (Conditions may be added, eliminated, altered, or modified)

#### **Attachments**

- 1. Amended Site Development Plan
- 2. Amended Landscape Plan
- 3. Amended Architectural Elevations
- 4. Architect's Statement of Design






AVID A. KASTER, NCARB, LEED—A. ICHAEL L. HOWARD, ARCHITECT
304 WEST 130th STREET
UITE 170
VERLAND PARK, KANSAS 66213
ELEPHONE (913) 681–1806
AXI (913) 681–1866
AXI (913) 681–1866

NI SIDELLEV WELLSV

YAYAS EURO BISTROBANQUET ROOM ADDITIO

DATE OCT 24, 2018
REVISED
SHEET NUMBER


KAI JOB NO. 1706-A




## EXISTING CONDITIONS + DEMO NOTES:


- 1. Contractor shall stake clearing limits to coordinate the locations for tree protection measures and tree protection fencing installation.
- 2. Contractor shall build and maintain temporary fences of brightly colored plastic tree protection fencing and signage so that construction workers can clearly see zones from where equipment must be kept clear. Signage will indicate "DO NOT ENTER", "DO NOT REMOVE", or other messages that communicate the importance of the tree protection fencing. Tree protection fence must be maintained at all times. It cannot be removed at any time during the construction. Upon completion of construction, all barriers, fencing and debris shall be removed from the site by the Contractor.
- 3. No clearing or grading shall begin in any area of construction site where tree preservation measures have not been completed.
- 4. No construction equipment can be operated within tree protection zone (TPZ) of the trees that are to be protected. Access to fenced preservation areas by construction equipment, materials or individuals that may cause harm to protected trees is prohibited.
- Contractor will be prohibited from cutting into tree's roots, compacting the soil over roots, or changing the ground level around the tree during construction. Root pruning, a tree protection measure, must be completed by qualified experts (forester or arborist) prior to any construction.
- 6. Attachment of any signage or fencing to any tree is strictly prohibited.
- 7. See Sheet L2 for Tree Protection Plan + Tree Protection Measures.
- 8. See Sheet L3 for proposed Landscape Plan..

COPYRIGHT © DG2 DESIGN 4835 MO 109, SUITE 102 EUREKA, MO 63025 TEL: 636.549.9007 DG2 DESIGN MISSOURI STATE CERTIFICATE OF AUTHORITY #LC1126925 Bistro Euro aya NO. ISSUED FOR DATE Landscape Architect LA-2010000189 DRAWING TITLE




EXISTING
SITE + DEMO PLAN
PROJECT #: 18-299
SHEET NUMBER





# BANQUET ROOM ADDITION NORTHWEST ELEVATION

SCALE // 1/4" = 1'-0"



BANQUET ROOM ADDITION NORTHEAST ELEVATION SCALE // |/4" = |'-0"

BANQUET ROOM ADDITION SOUTHEAST ELEVATION

KASTER NUMBER A-200200276

BISTRO BLVD. MISSOURI EURO LIVI 0 8 156 ESTI

OCT 19, 2018 REVISED

SHEET NUMBER SHEETS

KAI JOB NO. 1706-A

SCALE // |/4" = |'-0"





## KASTER ARCHITECTS, INC

Roger A. Kaster, David A. Kaster, NCARB, Michael L. Howard. Ph: 913-681-1200, Fax: 913-681-1866 7304 West 130th Street – Suite 170 Overland Park, Kansas 66213

November 21, 2018

# YAYAS EUROBISTRO – BANQUET ROOM ADDITION CHESTERFIELD, MO 15601 Olive Boulevard Chesterfield, MO

#### ARCHITECT'S STATEMENT OF DESIGN

The overall goal of this project is to add a 1,200 square foot banquet room to an existing Yayas Restaurant. The existing restaurant sits on a pad site to the north side of Olive Boulevard northeast of the Chesterfield Mall property across Highway 64. The existing building is a single-story restaurant with EIFS facades and a mansard consisting of standing seam metal roof which screens the roof top units. There is a patio at the northeast surrounded by a low site wall. The area of the building facing the patio features a flat roof projecting out under the mansard with EIFS banding and dark-bronze framed storefront windows. The storefront windows are set in slight recesses giving the vertical EIFS pilasters between them a thickened appearance.

The goal of our Banquet Room Addition is to make it look as if it has always been part of the building. To accomplish this, our design replicates the design features of the existing building. We will match the dark bronze framed storefront windows and thickened pilasters and mass brackets. Glazing will match the existing glazing panels at the patio. EIFS will be the new material on the facades with thickened EIFS bands to align with the existing building. Top of wall and coping will match existing and a new mansard roof screen to match existing will connected to the existing mansard and extended over the new banquet room.

Mechanical units for the addition will be set behind the metal mansard to ensure the units are fully screened.

There will necessarily be an egress from the Banquet Room. The door will be integrated into the storefront windows matching the patio door. A portion of the site wall surrounding the patio will be removed and the patio extended into the area southeast of the Banquet Room Addition to integrate the patio into the addition. Materials for the patio and new site wall surrounding the patio will match the existing and wall finishes including the site wall height. A portion of the existing sidewalk along the northeast of the site will be removed for the installation of the addition and a new landscape bed. An entirely new landscape plan is being submitted retaining the healthy plantings and trees that exist on site. Other trees and plantings are indicated on the plans to meet the development ordinance in close consultation with City of Chesterfield Planning Staff.

No exterior building lighting (other than an emergency fixture at the egress door) will be on the addition. All existing site and building lighting is existing to remain. No exterior signage will be placed on the addition or added to the site. All existing site signage is to remain.

Thank you.

Mila I Jan

Michael Howard - Project Manager, Kaster Architects